





Video on Youtube: [Click here !](#)

## Standard Operation Procedures – Muntin Bar Mounting

<p>1 Check window bars from your supplier before using them for flatness, <b>pressure marks</b> on the liner, liner lifting and accurate sealing lips.</p> <p>Do not use defective parts of the profile.</p>	<p><b>Pressure marks</b></p>      <p><b>Concavity</b></p>
<p>2 Avoid the <b>liner flagging</b> off at the edges and pollution of the adhesive during your cutting or grooving process. <b>Cut through the liner first</b> for best results. Change the saw blade.</p>	<p><b>Lifting the release film and pollution of adhesive surface</b></p>  
<p>3 Verify the good fit of the pre-cut part into the window frame before removing the liner. Leave</p>	

<p><b>a gap</b> at each end.#</p> <p>The <b>minimum gap of 0,25mm</b> works for parts of short length. Calculate the extension gap with help of the table for integration temperatures if you are working with longer parts. <b>(see Video example and attachment)</b></p> <p>If the parts are too long, do not push in by force but re-work the length.</p>	 <p><b>Tilting of the Profile. No Contact of the adhesive to the glass through overlapping sealing lips results in an unstable adhesion.</b></p> <p><b>Good Fit of the Profile Contact of the adhesive to the glass results in a safe adhesion.</b></p>
<p>4 Wait until the window has reached shop floor temperature in order to avoid condensation water on the glass. The <b>minimum application temperature is 15°C.</b></p>	<p><b>Application temperature:</b></p>  <p><b>optimum temperature = 25°C</b> minimum temperature = 15°C)</p> <p>Windows and profiles must have the same application temperature.</p> <p>Before using them store both materials for 12 hours in the same room.</p>
<p>5 <b>Use isopropanol</b> or an Industry <b>Cleaner</b> for example <b>Tesa Industrial Cleaner.</b></p> <p>Use <b>clean towels</b> in order to clean the window glass from dust and grease.</p> <p>Let dry off 30 seconds.</p>	<p><b>Glass cleaning: Remove residues for secure adhesion</b></p>  <p>The surface tension of the glass can be tested with test-inks and test-pens.</p>
<p>6 For positioning</p>	<p><b>Positioning: for long profiles, glue the ends first</b></p>

<p>of <b>long window bars</b>, remove a small piece of liner at each end of the part. Use a distance piece in order to <b>ensure a gap to the frame</b>. Place on the window pane and pull the liner out off the gap. Then apply pressure by hand.</p> <p><b>Attention:</b> Through permanent change of lengths and <b>adhesion failures</b> the adhesive strength may be reduced, and profiles tend to lift from the glass.</p>	 <p>If bars are cut too long or profiles are not cut free, the adhesive does not glue at the end. A lifting take-up must be avoided.</p> <p>In regions with permanent changing climatic conditions, the use of an MS Polymer glue at each end of the profile or a high performance adhesive like ACX-Plus can be usefull.</p>
<p>7 Apply <b>pressure</b> to the window bar by the heel of the hand. Start at one end and <b>push strongly</b> each 10 cm until the other end Or use a pressure roller like shown in the picture</p>	<p><b>Adhesion:</b></p>   <p>If Profiles extend 1m enclosed metal inserts should be existent to stabilize the glass. <b>Attention!</b> Through multiple glazing the glass pane may be thinner than usual. Through extreme compacting pressure the glass draws back and results in an unstable adhesion.</p>
<p>8 Let the adhesive dwell to the glass for <b>24 hours before shipment or outdoor storage.</b></p>	<p><b>Rest period after bonding</b></p> 

**Attachment – Calculating the extension gap**

### 3. ACCURACY OF FIT

$$\text{extension gap} = 0.084 * \text{Delta} * t * \text{Length} / 2$$

(gap at each end)

coefficient for extension

difference in temperature

Calculate the extension gap for each end with help of the table for integration temperatures. The value **0.084** is the coefficient for extension in this formula. **Delta\*t** is the difference in temperature, of an integration temperature to the highest temperature in the summer.

### 3. ACCURACY OF FIT

$$\text{extension gap} = 0,084 * \text{Delta} * t * \text{Length} / 2 \text{ (gap at each end)}$$

LENGTH IN METER	INTEGRATION TEMPERATURE [C°]						
	5	10	15	20	25	30	35
0.5	1.6	1.5	1.4	1.3	1.2	1.1	0.9
1	3.2	2.9	2.7	2.5	2.3	2.1	1.9
1.5	4.7	4.4	4.1	3.8	3.5	3.2	2.8
2	6.3	5.9	5.5	5.0	4.6	4.2	3.8
2.5	7.9	7.4	6.8	6.3	5.8	5.3	4.7
3	9.5	8.8	8.2	7.6	6.9	6.3	5.7
3.5	11.0	10.3	9.6	8.8	8.1	7.4	6.6
4	12.6	11.8	10.9	10.1	9.2	8.4	7.6

$$\text{Delta} * t: 35^{\circ}\text{C} - 15^{\circ}\text{C} = 20$$

**Example:** An integration temperature of 15°C and a maximum temperature of 35°C in the summer, results in the value 20 for Delta\*t.

### 3. ACCURACY OF FIT

extension gap =  $0,084 * \Delta t * \text{Length} / 2$  (gap at each end)

LENGTH IN METER	INTEGRATION TEMPERATURE [C°]						
	5	10	15	20	25	30	35
0.5	1.6	1.5	1.4	1.3	1.2	1.1	0.9
1	3.2	2.9	2.7	2.5	2.3	2.1	1.9
1.5	4.7	4.4	4.1	3.8	3.5	3.2	2.8
2	6.3	5.9	5.5	5.0	4.6	4.2	3.8
2.5	7.9	7.4	6.8	6.3	5.8	5.3	4.7
3	9.5	8.8	8.2	7.6	6.9	6.3	5.7
3.5	11.0	10.3	9.6	8.8	8.1	7.4	6.6
4	12.6	11.8	10.9	10.1	9.2	8.4	7.6

extension gap =  $0.084 * 20 * 2 / 2 = 1.68$  mm (gap at each end)

**Example:** With a part of 2m length this results in an extension gap of 1.68mm at each end.

### 3. ACCURACY OF FIT

extension gap =  $0,084 * \Delta t * \text{Length} / 2$  (gap at each end)

LENGTH IN METER	INTEGRATION TEMPERATURE [C°]						
	5	10	15	20	25	30	35
0.5	1.6	1.5	1.4	1.3	1.2	1.1	0.9
1	3.2	2.9	2.7	2.5	2.3	2.1	1.9
1.5	4.7	4.4	4.1	3.8	3.5	3.2	2.8
2	6.3	5.9	5.5	5.0	4.6	4.2	3.8
2.5	7.9	7.4	6.8	6.3	5.8	5.3	4.7
3	9.5	8.8	8.2	7.6	6.9	6.3	5.7
3.5	11.0	10.3	9.6	8.8	8.1	7.4	6.6
4	12.6	11.8	10.9	10.1	9.2	8.4	7.6

extension gap =  $0.084 * 20 * 2 / 2 = 1.68$  mm (gap at each end)

$5.5 - 3.8 = 1.7$  mm (rounded value)

**Example:** As an alternative use the extension values of the table for your calculation.  
For our example this results in the rounded value of 1.7mm at each end.